



**МИНИСТЕРСТВО ТРАНСПОРТА
РОССИЙСКОЙ ФЕДЕРАЦИИ**
(МИНТРАНС РОССИИ)

**ФЕДЕРАЛЬНОЕ АГЕНТСТВО
ВОЗДУШНОГО ТРАНСПОРТА**
(РОСАВИАЦИЯ)

Ленинградский проспект, д. 37, Москва,
А-167, ГСП-3, 125993, Телетайп 111495
Тел. (499) 231-50-09 Факс (499) 231-55-35
e-mail: rusavia@scaa.ru

Руководителям Межрегиональных
территориальных управлений
воздушного транспорта Федерального
агентства воздушного транспорта

Организациям по списку














17.01.2019 № Исх-943/03



На № _____ от _____

Информационное письмо ДЛГ-01-2019

Управление поддержания летной годности воздушных судов информирует эксплуатантов воздушных судов о выпуске иностранными авиационными администрациями следующих Директив летной годности за период 17.12.2018 – 13.01.2019:

№	Номер	Выпущено страной	Дата выпуска	Изготовитель ВС	Тип ВС (Классификация ВС, страны выпустившей ДЛГ)	Краткое содержание
1	2018-0276R1		11.01.2019	AIRBUS	A330	Fuselage - Structural Parts / Joints - Modification / Reinforcement
2	US-2018-26-05		11.01.2019	BOEING	777	Fuel - Motor-Operated Valve Actuators / Maintenance or Inspection Program - Inspection / Replacement / Revision
3	US-2018-26-06		11.01.2019	BOEING	737	Doors - Main Landing Gear Center Door Assemblies - Inspection
4	US-2018-26-03		11.01.2019	BOEING	757	Equipment / Furnishings - IPECO 3A090 and 3A258 Flight Crew Seats - Inspection
5	US-2018-22-07		11.01.2019	ENGINE ALLIANCE LLC	GP7200	Engine - High Pressure Compressor Stages 2-5 Spool - Inspection / Replacement
6	2019-0002		11.01.2019	AIRBUS	A380	Nacelles / Pylons - Inboard and Outboard Pylon Drain System - Inspection
7	US-2018-23-12		11.01.2019	APPLIANCES	ATA 25 EQUIPMENT / FURNISHINGS	[Correction] ZODIAC AERO EVACUATION SYSTEMS - Fusible Plugs - Replacement
8	2019-0004		11.01.2019	APPLIANCES	ATA 34	THALES AVS FRANCE SAS -

					NAVIGATION	Global Navigation Satellite System - Operational Limitations
9	2019-0003		11.01.2019	AIRBUS HELICOPTERS	EC175	Rotor Drive - Main Gearbox Top Sensor - Inspection
10	CF-2019-02		10.01.2019	VIKING AIR LTD	DHC-6 (Twin Otter)	Time Limits / Maintenance Checks - Airworthiness Limitations - Implementation
11	CF-2019-01		10.01.2019	AIRBUS HELICOPTERS, BELL HELICOPTER TEXTRON CANADA (BHTC), BELLIS INVESTMENTS LTD, MD HELICOPTERS INC (MDHI)	AS 350 / EC 130, AS 355, 206, 407, STC SH98-35, 369, 500N	Standard Practices - Helicopter External Transport System (HETSБ,Ÿ) - Unapproved Parts, Inadequate Service Life Limits and Maintenance Requirements
12	CF-2018-36		10.01.2019	BOMBARDIER	CL-600 (Challenger)	Navigation - Flight Instruments - Unreliable Air Data in the Cockpit
13	2019-0001		10.01.2019	AIRBUS HELICOPTERS	AS 350 / EC 130	Doors - Sliding Door Opening Mechanism - Inspection
14	2018-0265R1		10.01.2019	BRP-ROTAX GmbH & Co KG	914 F, 915	[Correction] Engine - Exhaust Valve - Replacement
15	2018-0137R1		09.01.2019	AIRBUS	A318, A319, A320, A321	Nacelles / Pylons - Pylon Aft Fixed Fairings - Inspection
16	CF-2018-37		08.01.2019	BOMBARDIER	BD-100	Recording System - Cockpit Voice Recorder (CVR) and Flight Data Recorder (FDR) power supply modification
17	US-2018-25-17		07.01.2019	AIR COMM CORPORATION, AIRBUS HELICOPTERS, BELL HELICOPTER TEXTRON CANADA (BHTC)	CAA UK AAN 25273, EASA STC 10029555, STC EASA.IM.R.S.01173, STC EASA.IM.R.S.01537, STC SH2750NM, STC SR00222DE, STC SR00543DE, STC SR00643DE, AS 350 / EC 130, 206, 407	Air Conditioning - Electrical Connectors - Replacement
18	2018-0292		28.12.2018	LEONARDO S.p.A. HELICOPTERS	AB139/AW139	Tail Rotor - Tail Rotor Slider Assembly - Inspection
19	2018-0290		21.12.2018	AIRBUS	A350	Stabilizer - Vertical Stabilizer Tension Bolts - Modification
20	2018-0291		21.12.2018	ROLLS-ROYCE PLC	RB211 TRENT 700	Engine - High Pressure Turbine Blades - Replacement
21	CF-2018-33		21.12.2018	BOMBARDIER, ROCKWELL COLLINS	CL-600 (Regional Jet), EASA STC 10041711, STC ST01514WI-D	Avionic System - Airplane Flight Manual Navigation System Limitations - Prohibit Editing CLIMB TO Altitudes and Use of Temperature Compensation on


						Flight Management System
22	2018-0288		21.12.2018	AIRBUS	A318, A319, A320, A321	Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2 - Damage Tolerant Airworthiness Limitation Items - Implementation
23	2018-0289		21.12.2018	AIRBUS	A318, A319, A320, A321	Fuselage - Service Door Stop Fitting Hole - Inspection / Repair
24	2018-0283		20.12.2018	AIRBUS HELICOPTERS DEUTSCHLAND	MBB-BK 117	Rotors Flight Control - Main Rotor Actuator - Inspection
25	2018-0286		20.12.2018	ENSTROM HELICOPTER CORPORATION	280, 480, F-28	Main Rotor - Hydraulic Damper / Belt Tension Shaft Rod End Assembly - Inspection
26	2016-0106R1		20.12.2018	AIRBUS	A321	Fuselage - Frame 35.2A - Inspection
27	2018-0284		20.12.2018	AIRBUS HELICOPTERS DEUTSCHLAND	EC135/635	Rotors Flight Control - Main Rotor Actuator - Inspection
28	CF-2018-35		20.12.2018	BELL HELICOPTER TEXTRON CANADA (BHCTC)	429	Tail Rotor Drive - Tail Rotor Gearbox - Introduction of Attachment Hardware Recurring Torque Check
29	2018-0287		20.12.2018	AIRBUS HELICOPTERS	AS 350 / EC 130, AS 355	Rotors Flight Control - Tail Rotor Gearbox Actuating Rod - Inspection
30	CF-2018-34		20.12.2018	BOMBARDIER	DHC-8	Flight Controls - Elevator Power Control Unit Bracket Cracking
31	2018-0285		20.12.2018	PILATUS AIRCRAFT LTD	PC-6	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
32	2018-0282		19.12.2018	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Fuselage - Main Gearbox Suspension Bar Rear Attachment Fitting Screws - Inspection
33	DCA-750XL-32A		19.12.2018	PACIFIC AEROSPACE LTD	750XL	Landing Gear - Nose and Main Landing Gear Attachment Bolts - Inspection
34	DCA-750XL-33		19.12.2018	PACIFIC AEROSPACE LTD	750XL	Aileron Pivot Fork Assembly - Inspection
35	2018-0281		18.12.2018	PIPISTREL VERTICAL SOLUTIONS d.o.o.	Virus SW 121	Fuel - Fuel Pressure Sensor - Inspection / Replacement
36	2018-0264		17.12.2018	DASSAULT AVIATION	Falcon 7X	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
37	2018-0280		17.12.2018	LEONARDO S.p.A. HELICOPTERS	A109/A119	Rotors Flight Control - Mixing Control System Rigid Connecting Link - Inspection

Тексты Директив летной годности находятся на интернет - ресурсах соответствующих авиационных администраций и разработчиков АТ.

Руководителям Межрегиональных территориальных управлений воздушного транспорта Федерального агентства воздушного транспорта довести данную информацию до подконтрольных авиапредприятий Российской Федерации.

Организациям, эксплуатирующие указанные ВС, принять меры по своевременному выполнению требований применимых директив летной годности.

Начальник Управления
поддержания летной годности
воздушных судов



В.В. Кудинов

Соловьев Артем Александрович
495 645 85 55 доб. 53-37